

DRUM GREASE SYSTEM

MODELS 2022 - 635

Version 1.1



| ID | Part Number | Description | Model | MFG |
|----|-------------|--------------------------|-----------|-----|
| 1 | 113680A1 | Tube Supply Rear | 2022-2044 | OEM |
| 2 | 113682A1 | Tube Rotor Upper Rear | 2022-2055 | OEM |
| 3 | 113685A1 | Tube Front Rotor | 2022-2055 | OEM |
| 4 | 113687A1 | Tube Front Rotor | 2155-635 | OEM |
| 5 | 122595A1 | Adapter | 2155-635 | OEM |
| 6 | 1339376C1 | Fitting | 2022-2044 | OEM |
| 7 | 1546332C2 | Grease Lower Rear | 2022-635 | OEM |
| 8 | 1968092C1 | Clamp | 2022-2044 | OEM |
| 9 | 1982834C1 | Adapter | 2022-2055 | OEM |
| 10 | 1982874C1 | Tube Lower Rear | 2022-2044 | OEM |
| 11 | 1984333C1 | Rotor Grease Supply R.H. | 2022-635 | OEM |
| 12 | 1984338C1 | Tube Front Vertical | 2022-2055 | OEM |
| 13 | 1984408C1 | Tube Rotor | 2022-635 | OEM |
| 14 | 198823C1 | Grommet | 2055-635 | OEM |
| 15 | 1988701C1 | Tube Upper Front | 2022-2044 | OEM |
| 16 | 1988702C1 | Tube Upper Front R.H. | 2022-635 | OEM |
| 17 | 1988703C | Tube Gear Lower Front | 2022-2044 | OEM |
| 18 | 1988704C1 | Tube Lower Front R.H. | 2022-635 | OEM |
| 19 | 1988705C2 | Tube Gear Upper Rear | 2022-2044 | OEM |
| 20 | 1988706C1 | Tube Upper Rear | 2022-635 | OEM |
| 21 | 1988718C1 | Spacer | 2022-2555 | OEM |

| ID | Part Number | Description | Model | MFG |
|----|-------------|-----------------|-----------|-----|
| 22 | 1990056C1 | Fitting | 2022-635 | OEM |
| 23 | 1994951C1 | Fitting | 2022-2055 | OEM |
| 24 | 217-117 | Fitting | 2022-2055 | OEM |
| 25 | 217-27 | Fitting | 2022-2055 | OEM |
| 26 | 241971 | Adapter | 2022-2055 | OEM |
| 27 | 253449 | Elbow | 2022-635 | OEM |
| 28 | 495-11059 | Fitting | 2022-2055 | OEM |
| 29 | 495-81170 | Washer | 2022-635 | OEM |
| 30 | 515-2148 | Clamp | 2555-635 | OEM |
| 31 | 578384 | Elbow | 2022-635 | OEM |
| 32 | 76085536 | Lock Nut - 1/8 | 2022-635 | OEM |
| 33 | 76355 | Tee | 2022-635 | OEM |
| 34 | 86513087 | Fitting | 2022-2055 | OEM |
| 35 | 87016 | Washer | 2022-635 | OEM |
| 36 | 87381288 | Lock Nut - 9/16 | 2022-635 | OEM |
| 37 | 87414 | Fitting | 2022-635 | OEM |
| 38 | 9706918 | Fitting | 2022-635 | OEM |
| 39 | 9841829 | Fitting | 2155-635 | OEM |
| 40 | A38799 | Clamp | 2055-2155 | OEM |

NOTES:

- 1. 113680A1 REPLACES 1984336C1
AND 1984340C1
- 2. 113682A1 REPLACES 1984337C1
AND 1984341C1
- 3. 113685A1 REPLACES 1984334C1
- 4. 113687A1 REPLACES 1984335C1
- 26. 241971 REPLACES 218-463
- 27. 253449 REPLACES 218-693
- 31. 578384 REPLACES 218-483
- 32. 76085536 REPLACES F53473
- 33. 76355 REPLACES 218-593
- 34. 86513087 REPLACES 218-673
- 35. 87016 REPLACES 495-11041
- 36. 87381288 REPLACES 218-1254
- 37. 87414 REPLACES 219-8
- 38. 9706918 REPLACES 218-443
- 39. 9841829 REPLACES 217-180