


DOFFER ASSEMBLY

MODELS 2022- 635

Version 1.1



EMAIL: INFO@RMKING.COM
TEL: 559.266.0258

DOFFER ASSEMBLY

MODELS 2022- 635

Version 1.1

| ID | Part Number | Description | Model | MFG |
|----|-------------|--------------|-----------|-----|
| 1 | 123175A1 | Doffer | 2022-2155 | OEM |
| 2 | 126-113 | Key | 2022-635 | OEM |
| 3 | 128658A1 | Nut Slotted | 2022-2055 | OEM |
| 4 | 1329439C1 | Disc | 2022-635 | OEM |
| 5 | 1339066C1 | Bearing Cap | 2022-635 | OEM |
| 6 | 1982374C1 | Shaft | 2022-635 | RMK |
| 7 | 1982375C1 | Doffer Shaft | 2022-635 | RMK |
| 8 | 223977C1 | Plate | 2022-635 | OEM |
| 9 | 25-1312 | Nut Slotted | 2022-2055 | RMK |
| 10 | 37-1614 | Dowel | 2022-635 | RMK |
| 11 | 383311A1 | Doffer | 2555-635 | RMK |
| 12 | 457400R1 | Key | 2022-635 | OEM |
| 13 | 669806R2 | Doffer Cup | 2022-635 | RMK |

| ID | Part Number | Description | Model | MFG |
|----|-------------|-------------------|------------|-----|
| 14 | 80680 | Lock Washer - 3/8 | 2022-635 | RMK |
| 15 | 86624186 | Washer | CPX420-635 | OEM |
| 16 | 86625241 | Washer | 2022-2555 | OEM |
| 17 | 87282C1 | Spacer | 2022-635 | OEM |
| 18 | 87395 | Pin | 2022-635 | OEM |
| 19 | 87440726 | Bearing | 2022-635 | RMK |
| 20 | 87613198 | Washer | CPX420-635 | OEM |
| 21 | 88206 | Bolt - 3/8 x 1 | 2022-635 | RMK |
| 22 | 88814 | Bolt - 3/8 x 1/2 | 2022-635 | RMK |
| 23 | 95-81056 | Washer | 2022-2555 | OEM |
| 24 | 9628503 | Nut - 3/8 | 2022-635 | RMK |

NOTES:

1. 123175A1 REPLACES 204710C2
7. 1982375C1 REPLACES 131435A1
14. 80680 REPLACES 492-11038
15. 86624186 REPLACES 496-41041
16. 86625241 REPLACES 496-21041
18. 87395 REPLACES 432-820
19. 87440726 REPLACES 669807R91
20. 87613198 REPLACES 495-81039
21. 88206 REPLACES 413-616
22. 88814 REPLACES 413-68
24. 9628503 REPLACES 425-106

EMAIL: INFO@RMKING.COM
TEL: 559.266.0258